



NRNT7.E336137 Switches, Industrial Control Certified for Canada

[Page Bottom](#)

Switches, Industrial Control Certified for Canada

[See General Information for Switches, Industrial Control Certified for Canada](#)

ELOBAU GMBH & CO KG
Zeppelinstrasse 44
88299 Leutkirch, GERMANY

E336137

Investigated to CAN/CSA C22.2 No. 14-13

Accessory Model(s) 153MBK or 165MBK, followed by 0, 1, 2, 3 or 4, followed by 0, followed by 0 or 1, may be followed by two digits.

Enclosed, Magnetically operated (reed) switches Model(s) 153MSK or 165MSK, followed by 0 or 1, followed by 0, followed by H, J or K, followed by 1, followed by A, B, C, D, E, F, H, J, K or L, may be followed by two or three digits

Investigated to CAN/CSA C22.2. No. 14-10

Limit switches Model(s) ZD followed by R or A, followed by 1 or 2, followed by 0, 1 or 2, followed by 1, 2, 3 or 4, followed by 0, 1 or 2, followed by R, maybe followed by any combination of letters and/or alpha numeric suffixes.

ZP followed by R or A, followed by 1 or 2, followed by 0, 1 or 2, followed by 1, 2, 3 or 4, followed by 0, 1 or 2, followed by R, L, V or H, maybe followed by any combination of letters and/or alpha numeric suffixes.

ZS followed by R or A, followed by 1 or 2, followed by 0, 1 or 2, followed by 1, 2, 3 or 4, followed by 0, 1 or 2, followed by R, L, V or H, maybe followed by any combination of letters and/or alpha numeric suffixes.

ZT followed by R or A, followed by 1 or 2, followed by 0, 1 or 2, followed by 1, 2, 3 or 4, followed by 0, 1 or 2, followed by R, L, V or H, maybe followed by any combination of letters and/or alpha numeric suffixes.

Limit switches, Class 2 Model(s) ZD followed by R or A, followed by 1, followed by 0, 1 or 2, followed by 1, 2, 3 or 4, followed by 0, 1 or 2, followed by R, followed by any combination of letters and/or alpha numeric suffixes.

ZM followed by R or A, followed by 1, followed by 0 or 1, or 2, followed by 2 or 3, followed by 0, followed by R, L, V or H, maybe followed by any combination of letters and/or alpha numeric suffixes.

ZP followed by R or A, followed by 1, followed by 0, 1 or 2, followed by 1, 2, 3 or 4, followed by 0, 1 or 2, followed by R, followed by any combination of letters and/or alpha numeric suffixes.

ZS followed by R or A, followed by 1, followed by 0, 1 or 2, followed by 1, 2, 3 or 4, followed by 0, 1 or 2, followed by R, L, V or H, followed by any combination of letters and/or alpha numeric suffixes.

ZT followed by R or A, followed by 1, followed by 0, 1 or 2, followed by 1, 2, 3 or 4, followed by 0, 1 or 2, followed by R, L, V or H followed by any combination of letters and/or alpha numeric suffixes.

Note - Models are followed by any combination of alpha numeric suffixes.

[Last Updated](#) on 2015-06-18[Questions?](#)[Print this page](#)[Terms of Use](#)[Page Top](#)

© 2015 UL LLC

The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL's Follow-Up Service. Only those products bearing the UL Mark should be considered to be Certified and covered under UL's Follow-Up Service. Always look for the Mark on the product.

UL permits the reproduction of the material contained in the Online Certification Directory subject to the following conditions: 1. The Guide Information, Assemblies, Constructions, Designs, Systems, and/or Certifications (files) must be presented in their entirety and in a non-misleading manner, without any manipulation of the data (or drawings). 2. The statement "Reprinted from the Online Certifications Directory with permission from UL" must appear adjacent to the extracted material. In addition, the reprinted material must include a copyright notice in the following format: "© 2015 UL LLC".